

5" RPM/SDIG

MOLEX MX150: 33472-1201
SOCKET: 33012-3002
CAVITY PLUG: 343450001
18AWG WIRE

E:
BW
BW
BW
2 DT



incorrect pin out

IF HAVING ISSUE WITH TRIM
BEING PRESENT ON HONDA
ENSIGN 5 INCH GAUGES,
PLEASE CONFIRM HARNESS
PINOUTS TO THIS CORRECT
DIAGRAM

5" RPM/SDIG

MOLEX MX150: 33472-1201
SOCKET: 33012-3002
CAVITY PLUG: 343450001
18AWG WIRE

B
B
E
2 [



correct pin out