

CLEANING AND CARE:

Although uTOPIa® & uTOPIa HD™ is an extremely durable fabric, cleaning is still important & will extend the life of your top. Ensure tops are stored clean & dry to avoid mildew.

100% Solution dyed polyester topping

- Water-resistant • Breathable • Dimensional stability

DO's



- Soft bristle brush or garden hose
- Ivory® or Dawn® dish soap + water
- ALWAYS rinse w/**COLD** water and air dry

DON'Ts



- NO Power washers
- NO Hard brushes
- NO Hot water
- NO Full Strength Bleach
- NO Detergents

STEP 1:

Brush off dirt & hose down thoroughly. Use a solution of 2 ounces mild soap to 1 gallon warm water, **NOT** hot water.

STEP 2:

Clean with soft bristle brush or garden hose. Rinse thoroughly with cold water & air dry.

This process will easily remove most stains.

FOR STUBBORN STAINS/MILDEW

STEP 1:

Mix 1/2 cup of non-chlorine bleach, 1/4 cup mild soap & a gallon of warm water.

STEP 2:

Apply with spray bottle *directly* on topping (avoid overspraying). Let set for 20 minutes, then scrub lightly with soft bristle brush. Rinse thoroughly with cold water & air dry.

UTTOPPER[®]
100% SOLUTION-DYED TOPPING

UTTOPPER[®]
HEAVY DUTY TOPPING
H10[™]

SPRADLING[®]

www.spradlingvinyl.com/sim
800-247-9901